

Model: BOTTEGA CALIZA C-2(R10) L 59,6X59,6(A) Codes: 100348367 Water absorption: Bla - Porcelanico (E<=0.1%)



na DAPc<sup>®</sup> ración Ambiental de

DIMENSIONAL FEATURES UNE-EN ISO 10545-2				
Thickness	8.5 MM	+/-5%*		
Width	596 MM			
Length	596 MM			
Length and width deviation	Below 0.15%	+/-0.3%*		
Side straightness deviation	Below 0.15%	+/-0.3%*		
Squareness deviation	Below 0.15%	+/-0.3%*		
Surface flatness deviation	Below 0.15%	+/-0.4%*		
*ISO-13006:2018 UNE-EN 14411:2016				

	MECHANICAL FEATURES UNE-EN ISO 10545-4-6-7-11	
Breaking strength	2338.2 N	>1300N*
Modulus of rupture	54.8 N/MM2	>=35N/mm2*
Abrasion resistance	PEI 4 / 1500v	
Crazing resistance	Resists 3 cycles	
*ISO-13006:2018 UNE-EN 14411:2016		

	HYGIENIC FEATURES UNE-EN ISO 10545-13-14:1995	
Chemical resistance	Class "A" for swimming pools and cleaning products (resists attack). Minimum Class "B" for acids and bases	B Min.*
Stain resistance	Class 5. Easy cleaning with water	3 Min.*
*ISO-13006:2018 UNE-EN 14411:2016		

		ITI-SLIP VALUE 165: 2022 / ASTM C1028	
Dynamic coefficient of friction	>0,42		
Slip resistance (pendulum-wet)	CL2		
Slip resistance (ramp)	R-10		TONO 1 / ID 2408*
Slip resistance (bare feet)	С		TONO 1 / 18729*
*ISO-13006:2018 UNE-EN 14411:2016			

	PACKING	
Sales units per box	1.776073 M2/BOX	
Sales units per pallet	56.834328 M2/PAL	
Sales units per unit	0.355215 M2/PIECE	



150 5

SGS

SGS

SGS

Do not use cleaning agents containing hydrofluoric acid. It is recommended to fix tiles with a minimum joint of 1,5 mm. Do not fix without joint. For big sizes, it is recomended to fix with mortars containing polymeric additives and to use the double glueing technique. Mosaic tiles must be grouted. This document is only commercial and cannot be used as expert opinion, documentary evidence or in any legal or administrative procedure unless authorized by PORCELANOSA S.A.

## PORCELANOSA Grupo

## SCOPE OF USE

Technical code-1

6 - Use on heavy traffic floors

RECOMMENDED USE LOCATIONS
Single-family dwelling
External Premises: External staircases and ramps
Collective housing
Outdoor Premises: Uncovered Terraces (Accessible from outside)
Public Residential
Bathrooms in single or double rooms
Toilets in collective rooms, plant bathroom, office, service rooms maintenance plant
Teacher
Pre-school and Primary: Classroom with direct opening to the exterior
Pre-school and Primary: Playroom, exercise room, multi-purpose room with direct opening to the outside.
Secondary, Baccalaureate and University: Classroom with direct opening to the outside.
Secondary, Baccalaureate and University: Laboratories with aggressive chemicals
Public attendance
Catering: Drinks distribution outlet, automatic machines
Catering: Cooking in small restaurant, bar, cafeteria, cafeteria, company canteen
Entertainment and recreation: Showroom, cinema, theatre, sporting activities, amphitheatres, games (Indoor)
Common transit areas
Indoor premises: Public entrance hall and lifts, in hospital, administrative, public and similar activities.
Indoor premises: Main staircases and heavy duty ramps
Indoor premises: Main staircases and ramps for medium use
Service, facilities
Toilets for the public in public, commercial, educational or intensive-use buildings
Toilets for the public in medium-use buildings. Employee toilets
Collective sanitary facilities, changing rooms and showers
Heating, air-conditioning and other humid premises



Do not use cleaning agents containing hydrofluoric acid. It is recommended to fix tiles with a minimum joint of 1,5 mm. Do not fix without joint. For big sizes, it is recomended to fix with mortars containing polymeric additives and to use the double glueing technique. Mosaic tiles must be grouted. This document is only commercial and cannot be used as expert opinion, documentary evidence or in any legal or administrative procedure unless authorized by PORCELANOSA S.A.